



Części niezbędne do użycia zawieszki DP-45-MOC-ZO

Głowica (C)

Mocownik (B)



Przewód od głowicy (A)




Elementy niezbędne przy czynnościach montażowych:

- klucz ampulowy
- wiertarka


UWAGA! Lista produktów, z którymi współpracują wybrane akcesoria dostępna jest na stronie

1. Nawierć otwór o średnicy 5 mm w wybranym profilu.




Fi 5 mm


2. Zdejmij izolację na odcinku wprowadzanym do otworu śruby i wnętrza zawieszki. Przeciągnij przewód (A) przez otwóry w mocowniku (B) i głowicy (C). Podłącz zasilanie do taśmy LED. Osadź oprawę w mocowniku.




3. Wsuń pręt w mocownik głowicy (C). Zablokuj go dokręcając docisk kluczem ampulowym.



4. Podwieś oprawę na wybranym systemie do podwieszania i zasilania.






Parts needed to mount the DP-45-MOC-ZO fastener

Head (C)

Mounting bracket (B)



Head cable (A)




Tools needed for mounting:

- Allen wrench
- drill


NOTE! A list of products corresponding with the selected accessories is available

1. Drill a hole with a diameter of 5 mm in the selected extrusion.




Fi 5 mm

2. Remove the insulation on the section inserted inside the screw and the head. Run the cable (A) through the holes in the mounting bracket (B) and in the head (C). Connect power to the LED strip. Attach the lighting fixture to the mounting bracket.



3. Insert the rod into the mounting bracket of the head (C). Block it by tightening it with the Allen wrench.



4. Suspend the lighting fixture using a selected suspension and power supply system.

