

### Parts needed to mount the 45-ALU extrusion



Mounting bracket (A)



Extrusion (B)



LED strip (C)



Cover (D)



End Cap (E)


### Tools needed for mounting:

- drill
- screwdriver


**NOTE!** All LED strips must be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The manual presents the simplest mounting procedure.  
More mounting procedures and related accessories can be found at

- 1.** Feed the power cable. Attach the mounting bracket (A) to the surface with screws.



- 2.** Mount the LED strip (C) in the extrusion (B), insert the cover (D) and the end cap (E).



- 3.** Connect power to the LED strip and mount the extrusion (B) in the mounting bracket.

